



---

## Vehicle History

---

CANADA Dare

Phone: (804) 465-5423

Fax: (934) 355-5506

**Fleet ID#: 751**

---

**From WO#: 1**

Date: 12/7/2003 6:39:

Invoice Total: \$188.62

Odometer: 0

Hub: 2332500

**Invoices Total: \$188.62**

### Labour Details

Randy.. Check circuits for excessive resistance, check fuse panel for hot circuits.. Found 10 amp fuse replaced with 50 amp.

Changed to spec. Blew immediately when fan on high. Fan circuit drawing very high. Diagnosed bad bearing in fan. R&R. Very hard to get at.. Cleaned and derusted compartment and mounting bolts.

Brad..Check turned up a couple of missing wheel studs.. Replaced. Right rear signal light bulb replaced  
Clearance light center replaced .. Cleaned and lubricated sockets and springs. Note! Should come in for some brake work and a/c conversion to R-32

<u>Part Number:</u>	<u>Description:</u>	<u>Quantity:</u>
		2
56-2605	Fuse 20A	2
		1

---

**Thank you for your patronage!**